

**From:** Christina Adkins  
**To:** Brian Mechler  
**Cc:** [REDACTED]; [REDACTED]; [REDACTED] Lesley.French@oag.texas.gov; Austin.Kinghorn@oag.texas.gov; Charles Pinney  
**Subject:** Re: EVS 6030  
**Date:** Thursday, November 19, 2020 12:45:46 PM  
**Attachments:** image001.png

My understanding is that they are seeking it for all affected versions. I think it just needs to work it's way through the process administratively. I can reach out to the EAC to confirm.

And before you ask, we have a meeting with ESS in December to discuss the scope of this issue as it appears to have affected more systems than they initially disclosed to us.

---

**From:** Brian Mechler [REDACTED] >  
**Sent:** Thursday, November 19, 2020 12:32:37 PM  
**To:** Christina Adkins <CAdkins@sos.texas.gov>  
**Cc:** [REDACTED]  
[REDACTED] >; [REDACTED] >;  
Lesley.French@oag.texas.gov <Lesley.French@oag.texas.gov> [REDACTED]  
[REDACTED]; Austin.Kinghorn@oag.texas.gov <Austin.Kinghorn@oag.texas.gov>;  
Charles Pinney <CPinney@sos.texas.gov>  
**Subject:** Re: EVS 6030

**CAUTION:** This email originated from OUTSIDE of the SOS organization. Do not click on links or open attachments unless you are expecting the email and know that the content is safe. If you believe this to be a malicious or phishing email, please send this email as an attachment to [Informationsecurity@sos.texas.gov](mailto:Informationsecurity@sos.texas.gov).

**CAUTION:** This email originated from OUTSIDE of the SOS organization. Do not click on links or open attachments unless you are expecting the email and know that the content is safe. If you believe this to be a malicious or phishing email, please send this email as an attachment to [Informationsecurity@sos.texas.gov](mailto:Informationsecurity@sos.texas.gov).

Just in case anyone was worried or curious, the SYSLOAD.BMP file that failed the EVS 6.0.3.0 hash verification process does match with one of the previous FW versions, 1.4.1.2

I can't find anything on the ECO on the EAC website yet. The Pro V&V report lists a whole slew of affected versions, but the SLI report only identifies 6.0.3.0 as affected. Do we know for which versions ES&S is seeking EAC approval of the ECO?

Brian

On Wed, Nov 18, 2020 at 11:15 AM Christina Adkins <[CAdkins@sos.texas.gov](mailto:CAdkins@sos.texas.gov)> wrote:

Dear Examiners: